

# IMPORTANT SAFETY NOTICE

## ZIPP® 88 aluminum front hub



SRAM, LLC has determined that the hub flange and flange ring on the certain ZIPP 88 aluminum front hubs can fail, posing a crash risk and injury hazard. The affected ZIPP 88 hub model is readily identifiable by the design of the external flange ring which is pictured above.

Consumers with bicycle wheels equipped with potentially affected ZIPP 88 front hubs should stop riding immediately and return their wheel to SRAM or their local bicycle dealer for verification and to obtain a free replacement product.

Canadian Bicycle Dealers can process the replacement hub with:

Cycles Lambert

1-855-526-2378

Live to Play Sports

1-604-552-2930

This recall is being conducted in cooperation with Health Canada and the U.S. Consumer Product Safety Commission. Please display until march 6<sup>th</sup>, 2016.

For more information, please go to our websites: [www.SRAM.com](http://www.SRAM.com) and [www.ZIPP.com](http://www.ZIPP.com)

Retailer: Please post until \_\_\_\_\_, 2015.